DIAGRAM SHEET 4.5-4
QUICK DONNING HARNESS